



Manufacturer of products
**VISION[®]
CONTROL**

OPERATION & MAINTENANCE

MAINTENANCE INSTRUCTIONS

Cleaning and maintenance of glass:

- Routinely clean using ordinary window-washing techniques.
- For best results, use liquid glass cleaners or mild household detergents. Do not use cleaning compounds containing fluorine, strong acids, corrosive alkaline detergents or abrasives.
- To avoid damage, all potentially abrasive particles adhered to glass should be removed prior to cleaning. Razor blades or steel wool should never be used to scrape residue from glass surfaces.

Cleaning and maintenance of plastic crank handle or thumbwheel:

- If the crank handle becomes loose, just tighten the allen screw with an allen key on the side of the crank handle.
- Clean the crank handle or thumbwheel with cleaners used for PVC.

Cleaning and maintenance of aluminum blocks, oval plates, knobs, thumbwheels, moldings, and zinc crank handles:

- Mild soaps or detergents ruled safe for bare hands should be safe for coated aluminum. Stronger detergents such as some dishwasher detergents should be carefully spot tested. After cleaning, the finish should be thoroughly rinsed with clean water and dried.
- Avoid abrasive cleaners. Strong solvents or strong cleaner concentrations can cause damage to painted surfaces. Overcleaning or excessive rubbing can do more harm than good.
- Abrasive materials such as steel wool and abrasive brushes can wear and harm finishes. Do not scour painted surfaces.
- Never use paint removers, aggressive alkaline, acid or abrasive cleaners. Do not use trisodium phosphate, highly alkaline or highly acid cleaners. Always do a test surface.